ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID:	M 06419	Client:	Alaskan Copper Works
Date Received:	12/02/10	Project:	Metro Self Monitor M06419
Date Extracted:	12/07/10	Lab ID:	012031-01 x10
Date Analyzed:	12/08/10	Data File:	012031-01 x10.052
Matrix:	Water	Instrument:	ICPMS1
Units:	ug/L (ppb)	Operator:	AP

		Lower	Opper
Internal Standard:	% Recovery:	Limit:	Limit:
Germanium	97	60	125

Analyte:	Concentration ug/L (ppb)
Chromium	586
Nickel	603
Copper	359
Zinc	11.0

ENVIRONMENTAL CHEMISTS

Analysis For Total Metals By EPA Method 200.8

Client ID: Method Blank
Date Received: Not Applicable
Date Extracted: 12/07/10
Date Analyzed: 12/08/10
Matrix: Water
Units: ug/L (ppb)

Client: Alaskan Copper Works
Project: Metro Self Monitor M06419
Lob ID: 10.696 mb

Lab ID: I0-696 mb
Data File: I0-696 mb.040
Instrument: ICPMS1
Operator: AP

Lower Upper Internal Standard: % Recovery: Limit: Limit: Germanium 94 60 125

Concentration
ug/L (ppb)

Chromium <1
Nickel <1
Copper <1
Zinc <1

ENVIRONMENTAL CHEMISTS

Date of Report: 12/10/10 Date Received: 12/02/10

Project: Metro Self Monitor M06419, F&BI 012031

QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 012005-04 (Matrix Spike)

				Percent	Percent		
	Reporting	Spike	Sample	Recovery	Recovery	Acceptance	RPD
Analyte	Units	Level	Result	MS	MSD	Criteria	(Limit 20)
Chromium	ug/L (ppb)	20	1.11	87	89	67-132	2
Nickel	ug/L (ppb)	20	1.78	86	91	73-119	6
Copper	ug/L (ppb)	20	<1	87	90	50-144	3
Zinc	ug/L (ppb)	50	3.24	89	90	46-148	1

Laboratory Code: Laboratory Control Sample

	Percent									
	Reporting	Spike	Recovery	Acceptance						
Analyte	Units	Level	LCS	Criteria						
Chromium	ug/L (ppb)	20	101	66-135						
Nickel	ug/L (ppb)	20	107	67-134						
Copper	ug/L (ppb)	20	108	66-134						
Zinc	ug/L (ppb)	50	105	57-135						

ENVIRONMENTAL CHEMISTS

Data Qualifiers & Definitions

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probability.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb Analyte present in the blank and the sample.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht Analysis performed outside the method or client-specified holding time requirement.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- ${
 m jl}$ The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- js The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- $\,$ nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve Estimated concentration calculated for an analyte response above the valid instrument calibration range. A dilution is required to obtain an accurate quantification of the analyte.
- vo The value reported fell outside the control limits established for this analyte.
- x The sample chromatographic pattern does not resemble the fuel standard used for quantitation.

012031			SA	MPLE CHA	in of c	USTO	DY		ME	=	12/0	2/10)	A	14
Send Report To THOMPSON			SAMPLERS (signature)								Fage # of TURNAROUND TIME				
Company Acas Kan Copper Works Address 628 S. How Ford St			PROJECT NAME/NO. PO # METTO SECF MONITOR M 06419					,	Standard (2 Weeks) RUSH / Co/s Rush charges authorized by:						
City, State, ZIP SEATURE WA 98134 Phone # 206-571-6055 Fax # 206-382-4509			REMARKS								SAMPLE DISPOSAL □ Dispose after 30 days □ Return samples □ Will call with instructions				
Filotic # 200 - 17 0		300	7								ا است		call w	ith instr	ructions
	+								NALYS	SES RE	QUES	TED			~
Sample ID	Lab ID	Date	Time	Sample Type	# of containers	TPH-Diesel TPH-Gasoline	BTEX by 8021B	VOCs by 8260	SVOCS by 8270 HFS	CR CU MEZ				1	Notes
m 06419	01	12/2/10	11:15	H20	1					X					
Friedman & Bruya, Inc. 3012 16th Avenue West Seattle, WA 98119- 2000 Ph. (206) 285-8282	Received by Relinquished by	ans		Se Nh	PRINT PORD GA	NAME Thom	· Pso			COM	1PANY		12	DATE /z/n	TIME 17:00
	Received by:				4										
FORMS\COC\COC.DOC								- 11	-						J

ENVIRONMENTAL CHEMISTS

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

December 10, 2010

Gerry Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on December 2, 2010 from the Metro Self Monitor M06419, F&BI 012031 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Michael Erdahl Project Manager

Enclosures ACU1210R.DOC